

AGS

BMW MD1CS001

BMW Display Calibration

EDC17C50

EDC17CP45

Glow Plugs

Ford EDC16C3

Ford EDC16C34

Volvo EDC16C34

Hardcut

IMMO

- Alfa MM8GF
- BMW EDC17 (Not All)
- Fiat EDC15C7 (29F400)
- Fiat EDC16C39 (Full Read)
- Fiat Marelli 9GF (Flash)
- Hyundai - KIA EDC15C7
- Hyundai EDC17C53
- Iveco EDC17
- Jeep EDC16U31 Eeprom 4kb
- MAN EDC7C3 (8K Eeprom)
- Marelli 8F3 Revirgin Eprom 8kb
- Mini MED17.x
- Opel EDC17C18 - 19
- PSA EDC15
- PSA EDC17C10 EEprom
- PSA EDC17C60
- PSA MD1CS003
- Renault MD1CS006
- VAG EDC16U1 Eeprom
- VAG EDC17 - MED17
- VAG Marelli 4MV M95080 Eprom
- VAG ME7.5 (512 bytes Eeprom)
- VAG ME7.x.x Epprom
- VAG PPD1.5 Only
- VAG Simos7.1A - 16 Bit Eprom
- VAG Simos7.1A - 8 Bit Eprom

☐ MAF

- BMW EDC16C31 - 35
- Fiat EDC16C39
- Fiat Marelli 8F3
- Hyundai - KIA EDC17CP14
- MB CRD3x
- MB EDC16C2
- Renault EDC15C3
- VAG EDC15P
- VAG EDC16U34

☐ MovData (Under Development)

☐ NOREAD Remover

☐ NOX Sensor

- BMW - MSD80
- Mercedes DCM3.5
- Mercedes DCM3.5P
- Mercedes EDC17C66
- VAG MED7.1.1
- VAG MED7.5.10
- VAG MED7.5.11
- VAG MED9.5.10 FSI

☐ O2 Sensor

- Fiat EDC17C69
- Ford ME9.0C
- Land Rover Denso
- Opel ME7.6.1
- Peugeot IAW48P
- VAG ME7.1.1
- VAG ME75
- VAG MED9.5.10
- VAG Simos83 (P1116 - P1118)

☐ **OPF - GPF**

- BMW MEVD17x
- Fiat GPEC4 (GPF)
- Ford MG1CS015
- Ford MG1CS016
- Ford MG1CS017
- Hyundai - KIA CPEG3
- Hyundai - KIA GPEG2
- Mercedes MED17.7.x
- Nissan EMS3161
- Porsche MG1CS008
- Renault EMS3141
- Renault EMS3161
- VAG MED17.1.61
- VAG MG1CS008
- VAG MG1CS011
- VAG MG1CS111
- VAG Simos18.x
- VAG Simos19.x

☐ **PopBangs**

☐ **Readiness**

- BMW EDC17
- BMW MEVD17
- VAG EDC17 - MED17

☐ **Special Repairs**

- Fix Ford SID208 Gate problems
- MB EDC16C31 M55 Error fixer

Start - Stop

- ... BMW EDC17C50
- ... BMW EDC17C56
- ... BMW EDC17CP45
- ... BMW EDC17CP49
- ... BMW MD1CP002
- ... Citroen SID807EVO
- ... Ford MD1CS005
- ... Hyundai - KIA EDC17C57
- ... Mercedes EDC17C66
- ... Mercedes EDC17CP57
- ... Mercedes MED17.x
- ... PSA DCM6.2
- ... PSA SID807 (NoEvo)
- ... Renault EDC17C84
- ... Renault SID310
- ... VAG DCM6.2
- ... VAG EDC17C46
- ... VAG EDC17C64
- ... VAG EDC17C74
- ... VAG EDC17CP20
- ... VAG EDC17CP44
- ... VAG EDC17CP54
- ... VAG MD1CP004
- ... VAG MD1CP014
- ... VAG MD1CS004
- ... VAG MED17.5.5
- ... VAG MG1CS011
- ... VAG MG1CS111
- ... VAG PCR2.1
- ... VAG Simos18.x

☐ TPROT Remove (Tuning Protection)

- PSA EDC17C60
- VAG EDC17CP14
- VAG EDC17CP20
- VAG EDC17CP46
- VAG MED17.5

☐ TVA

- Alfa EDC16C39
- BMW EDC17C50
- EDC17C64
- Fiat EDC16C39 (Ducato)
- Hyundai - KIA EDC17C08
- Mercedes DCM3.5
- Mercedes EDC16CP31
- Opel EDC16C9
- VAG - Porsche EDC17CP44
- VAG EDC16CP34
- VAG EDC16U1
- VAG EDC17C46
- VAG PCR2.1

☐ Update Logs

☐ Water Pump Removing

- PCR2.1
- VAG EDC17C46 Water Pump
- VAG EDC17C54 Water Pump Temp Sensor
- VAG EDC17C64 Water Pump Temp Sensor
- VAG EDC17C74

☐ Y75 Removing

- Mercedes EDC15C7